ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	3	Atturu
Street ID	**Street Name**	**Significant Landmark**
W0513, W0416, W0515, W0511, W0519	NA, 5th Crs	Amba Bhavani Layout
Segment No.	**Total Length (m)**	
3/C-W0513/S085324	220.05	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	105.90	77.543241	13.097231	77.544193	13.097017	W0416	W0416
2	57.42	77.543895	13.097124	77.544010	13.097630	W0416	DEAD END
3	56.73	77.543638	13.097179	77.543748	13.097680	W0416	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains in Amba Bhavani Layout in ward no 03 Yelahanka Satellite Town Sub-Division Yelahanka zone	1000000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Roads and Drains in Amba Bhavani Layout in ward no 03 Yelahanka Satellite Town Sub-Division Yelahanka zone	003-16-000016
Work Order No.	**Work Order Date**	**Period of Extention**
EE (YNK.D) E-PMT-1/WO/80/2015-16	24/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
24/02/2016	23/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
SAMBHASHIVAREDDY		0.00
Phone No.	**E-Mail ID**	

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: W0513, W0416, W0515, W0511,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಯಲಹಂಕ ಉಪನಗರ ಉಪವಿಭಾಗ,
ಜಿ.ಬಿ.ಎಂ.ಪಿ. ಬೆಂಗಳೂರು-106

9972741359

Field Inspection Details

Number of Trees	Any Other Information	Name
2		PRADEEP
Date of Inspection	**Remarks**	
17/12/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0513, W0416, W0515, W0511,

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: W0513, W0416, W0515, W0511,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	17/12/2016	16/01/2017	COMPLETED
SE	VASU K M	17/12/2016	16/01/2017	COMPLETED
EE	VASU K M	17/12/2016	16/01/2017	COMPLETED
AEE	ASHOK	17/12/2016	16/01/2017	COMPLETED
AE	PRADEEP	17/12/2016	16/01/2017	COMPLETED
AE	PRADEEP	17/12/2016	16/01/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0513, W0416, W0515, W0511,